


FIG. 1

FIG. 2






FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7




FIG. 8






FIG. 9



	21°	21°		
<u>0</u>	$\uparrow 2$	$\rightarrow 1$		
<u>1</u>	$2a \rightarrow$	$1a \rightarrow$		
<u>2</u>	45°	45°		
<u>3</u>	$2 \rightarrow$	$1 \rightarrow$		
<u>4</u>	-45°	-45°		
<u>5</u>	21°	-21°		
<u>6</u>	45°	45°		
<u>7</u>	$2a' \rightarrow$	$1b' \rightarrow$		
<u>8</u>	0°	45°		
<u>9</u>	$2a \rightarrow$	$1b \rightarrow$		
<u>10</u>	45°	45°		
<u>11</u>	7°	7°		
<u>12</u>	-21°	-21°		
<u>13</u>	45°	45°		
<u>14</u>	$2a' \rightarrow$	$1b' \rightarrow$		
<u>15</u>	0°	45°		
<u>16</u>	$2a'' \rightarrow$	$1a'' \rightarrow$		
<u>17</u>	$2b' \rightarrow$	$1b' \rightarrow$		
	$2b'' \rightarrow$	$1b'' \rightarrow$		

FIG. 10






FIG. 11





	$15^\circ \quad 15^\circ$			
5				
12	$-15^\circ \quad -15^\circ$	$45^\circ \quad 45^\circ$		
13				
14	$2a' \quad 1a''$	$2b' \quad 1b''$		
7	$2a \quad 1a$	$2b \quad 1b$		
8				
9	$45^\circ \quad 45^\circ$	$45^\circ \quad 45^\circ$		
1				
0	$2 \rightarrow \uparrow 1$			
	$1' \cdot 2 \nearrow$			
	$0^\circ \quad 45^\circ$			
2				
3	$2 \rightarrow \quad 1 \rightarrow$			
4	$-45^\circ \quad -45^\circ$			

FIG. 12




FIG. 13




FIG. 14




FIG. 15




FIG. 16




FIG. 17




FIG. 18




FIG. 19




FIG. 20




FIG. 21




FIG. 22




FIG. 23





FIG. 24



glass plate located in upper
beam for PMD compensation




FIG. 25




FIG. 26




FIG. 27




FIG. 28





FIG. 29






FIG. 30

